

PART-II
SCHOOL BUILDING SAFETY CERTIFICATE

(To be filled by the S.D.E OF P.W.D. DEPARTMENT)

Name of the School D.V. D.V. Centenary Public School
Phillaur Dist. Vahindar

- 1.) This office Assistant Engineer/Junior Engineer visited the above mentioned School 02/5/24 and have visually inspected if for its safety and find it fit for normal use a school building.
- 2.) In case any addition or expansion and modification to this building h is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may be again be obtained after the completion from the undersigned.
- 3.) In case the building is effected by flood, or if there is settlement of walls / foundation or sagging of roofs etc. immediately inspection of the under signed be arranged to check the stability and the building safety of the building.
- 4.) This building is found visually safe hence it is expected that it can be safety occupied for normal use up to 31/2/25 (indicate year upto which it can be used).

Ref. No. 949

Dated. 02-05-2024.

Sl No. 11465671

Dt. 02-05-24.


Fees. - 15000/-


Sub Divisional Engineer
Construction Sub Division
PWD B & R Phillaur

PART-I
PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

(To be filled by the Head of School/ Instruction)

1. (a) Name of the School D.R.V. CENTENARY PUBLIC SCHOOL
PHILLAUR; DISTT- JALANDHAR
- (b) Level/Standard of School :- XII
- (c) Whether School is affiliated to C.B.S.E. or P.S.E.B. if affiliated then affiliation No. CBSE
2. Location Vill-Saifabad, PHILLAUR
3. Plot Area 4.5 Acres
4. Plinth Area 1.25 Acres
5. Number of Storey 3 (Three)
6. Year of construction of Building 1986
7. If the building has been constructed under the Supervision of the Qualified Engineer, the following details may be given
- a) Name of the Engineer with Qualification Sh. Sushil Chughary B-Tech (C)
- b) Address of the Engineer. 183, Gajral Nagar market
- c) Detail of structural drawings used in the construction Near T.V. Centre, Jalandhar
- d) Name & Address of Architect with qualification do-
8. Whether the building has been constructed for the purpose of
- a) School School
- b) Residential purpose and converted for use as a school NA
9. Material used for roofs
- a) R.C.C. slabs RCC Slabs
- b) R.S. Joints & Battens NA
- c) Wooden Joints & Battens NA
10. Material used for walls
- a) Mud mortar
- b) Cement mortar Cement
- c) Plaster i) Lime mortar
- ii) Cement mortar
11. Flooring:-
- a) Conglomerate Conglomerate
- b) Terrazo
- c) Brick paving
12. A detailed drawing indicating dimensions of the rooms alongwith size and location of doors and windows. Enclosed
13. Whether fire safety certificate obtained from concerned fire officer. Yes


Principal
D.R.V. D.A.V. Centenary
Public School
PHILLAUR (Jalandhar)

Signature and Stamp of the Head
of the School